














ADAPTER SYSTEM

| | | STS 130 | STS 260 | STS 260A | STS 400 | STS 750 | STA 300 | STA 550 |
|---|---|---------|---------|----------|---------|---------|---------|---------|
| Adapters and connectors for optimized machine and vacuum cleaner connection | | | | | | | | |
|  | Quick coupling nozzle 60-50 (Ref. No.: 617070) | | | | | | | |
|  | Quick coupling nozzle 60-70 (Ref. No.: 617279) | | | | | | | |
|  | Adapter connection G38/38 (Ref. No.: 617273) | | | | | | | |
|  | Adapter connection G38/50 (Ref. No.: 617054) | | | | | | | |
|  | Adapter connection G50/50 (Ref. No.: 617207) | | | | | | | |
|  | Adapter connection G70/70 (Ref. No.: 617268) | | | | | | | |
|  | Adapter connection 50/70 (Ref. No.: 617274) | | | | | | | |
|  | Adapter connection G50/76 (Ref. No.: 617267) | | | | | | | |
|  | Adapter connection G70/76 (Ref. No.: 617269) | | | | | | | |
|  | Hose connector G38/G38 (Ref. No.: 617272) | | | | | | | |
|  | Hose connector G50/G50 (Ref. No.: 617270) | | | | | | | |
|  | Hose connector G70/G70 (Ref. No.: 617271) | | | | | | | |
|  | Adapter connection 76/70 (Ref. No.: 617276) | | | | STS 40 | STS 75 | | |

GX/Y G = thread, X = suction-pad connection, Y = machine connection